BP PLC Form 6-K September 03, 2010

## SECURITIES AND EXCHANGE COMMISSION

Washington, D.C. 20549

Form 6-K

Report of Foreign Issuer

Pursuant to Rule 13a-16 or 15d-16 of the Securities Exchange Act of 1934

for the period ended September, 2010

BP p.l.c. (Translation of registrant's name into English)

1 ST JAMES'S SQUARE, LONDON, SW1Y 4PD, ENGLAND (Address of principal executive offices)

Indicate by check mark whether the registrant files or will file annual reports under cover Form 20-F or Form 40-F.

Form 20-F |X| Form 40-F

Indicate by check mark whether the registrant by furnishing the information

contained in this Form is also thereby furnishing the information to the Commission pursuant to Rule 12g3-2(b) under the Securities Exchange Act of 1934.

Yes	No	X

press release

September 3, 2010

#### UPDATE ON GULF OF MEXICO OIL SPILL

BP today provided an update on developments in the response to the MC252 oil well incident in the Gulf of Mexico. BP continues to work with the guidance and approval of the National Incident Commander and the leadership and direction of the federal government.

Subsea Source Control

The MC252 well has been shut-in since July 15. Following the completion of cementing operations on the well on August 5, pressure testing was performed which indicated there is an effective cement plug in the casing.

Operations are now underway to replace the Deepwater Horizon (DWH) drilling rig's failed blow-out preventer (BOP) with the DDII drilling rig's BOP in order to allow operations to complete the relief well to resume. The capping stack on top of the DWH BOP was removed by the drillship Discoverer Enterprise on September 2. Following the removal of the capping stack, the Q4000 support vessel will connect a riser to the DWH BOP as part of ongoing operations to remove the BOP from the well. The DDII drilling rig will then be expected to move its BOP into place.

The DDIII drilling rig is on standby in readiness to resume drilling the relief well. The well is at a measured depth of 17,909 feet and progressing to intersect with the MC252 well will involve drilling, alternating with ranging runs to confirm proximity to the well. Depending upon weather conditions, mid-September is the current estimate of the most likely date by which the relief well will intercept the MC252 well annulus.

Information on the subsea operational status is updated daily on BP's website, www.bp.com.

## Surface Spill Response

Since July 15, no new oil has flowed into the Gulf of Mexico from the MC252 well. No volumes of oily liquid have been recovered since July 21 and the last controlled burn operation occurred on July 20. BP, as part of Unified Command, continues to conduct overflights and other reconnaissance to search for oil on the surface.

Throughout the response, skimming operations recovered a total of over 826,000 barrels of oily liquid and a total of 411 controlled burns have been carried out, removing an estimated 265,000 barrels of oil from the open water.

At peak, approximately 3.5 million feet of containment boom was deployed in response to the oil spill. Currently 1.72 million feet of containment boom remains deployed.

Approximately 28,400 personnel, more than 4,050 vessels, and dozens of aircraft remain engaged in the response effort.

## Additional information

On August 23, the processing of all claims by individuals and businesses related to the Deepwater Horizon incident transferred to the Gulf Coast Claims Facility (GCCF) under the leadership of Ken Feinberg. Since the transfer, over 42,000 claims have been submitted to the GCCF, with over 4,900 claims totalling some \$38.5 million being paid. Prior to the transfer to the GCCF, BP had made 127,000 claims payments, totalling approximately \$399 million.

The cost of the response to date amounts to approximately \$8 billion, including the cost of the spill response, containment, relief well drilling, static kill and cementing, grants to the Gulf states, claims paid and federal costs. On June 16, BP announced an agreed package of measures, including the creation of a \$20 billion escrow account to satisfy certain obligations arising from the oil and gas spill.

---

BP Press Office London: +44 20 7496 4076 BP Press office, US: +1 281 366 0265 www.bp.com/gulfofmexicoresponse

- ENDS -

#### **SIGNATURES**

Pursuant to the requirements of the Securities Exchange Act of 1934, the registrant has duly caused this report to be signed on its behalf by the undersigned, thereunto duly authorized.

BP p.l.c. (Registrant)

Dated: 03 September 2010

/s/ D. J. PEARL
D. J. PEARL
Deputy Company Secretary